



How to Mount the RS-500 Sprayer as a Stand-Alone Unit



MOUNTING
BRACKET
PART # RS-500-6



- The sprayer should be installed within the weld cell at a convenient location. Be sure to consider movable fixtures and the confines of the robot.
- Each sprayer comes complete with all required installation hardware and mounting brackets.